IN THE UNITED STATES PATENT & TRADEMARK OFFICE

ATTORNEY DOCKET NUMBER: 200300138-1

IN RE APPLICATION OF; U.S. Patent No. 7,097,271

USPTO CONFIRMATION CODE: 8428

APPLICATION NO.: 10/672,424

FILED: Sep. 26, 2003

EXAMINER: Lamson Nguyen

GROUP ART UNIT: 2861

FOR: PRINTHEAD CALIBRATION

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

Sir:

The following is a request for a certificate of correction in Serial Number 10/672,424, now Patent Number 7,097,271.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

⊠ fee is:	All errors were the fault of the USPTO, no fee required. In the event that a further required, please charge the amount to Deposit Account No. 082025.
	All errors were the fault of the applicant and, accordingly, please charge \$100.00 Deposit Account No. 082025. In the event that a further fee is required, please the amount to the same Deposit Account.
	The errors were the fault of both the applicant and USPTO and, accordingly, charge <u>\$100.00</u> to our Deposit Account No. 082025. In the event that a further fee uired, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In column 10, line 20, in Claim 24, after "during" insert - - the - -. (Amendment to the claims filed on Jun. 6, 2006, page 6, in Claim 25, line 7)

In column 10, line 20, in Claim 24, after "more" insert -- normal --. (Amendment to the claims filed on Jun. 6, 2006, page 6, in Claim 25, line 7)

The requested corrections are attached on Form PTO 1050.

TATE

Respectfully Submitted

Name: Steven R. Ormiston Registration No.: 35974

Attorney/Agent of Record

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of I

PATENT NO.

: 7,097,271

APPLICATION NO.: 10/672,424

ISSUE DATE

: Aug. 29, 2006

INVENTOR(S)

: Volker Smektala et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 10, line 20, in Claim 24, after "during" insert - - the - -.

In column 10, line 20, in Claim 24, after "more" insert - - normal - -.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

HEWLETT-PACKARD COMPANY Intellectual Property Administration 3404 E. Harmony Road Mail Stop 35 Fort Collins, CO 80528

This collection of information is required by 37 CFR 1.322, and 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1459, Alexandria, VA 22313-1450, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patent, P.O. Bax 1450, Alexandria, VA 22313-1450.